



Tip M1/AU-A

Tip M1/AU-B

Tip M2/AU-A

Tip M2/AU-B

Tip M1/AU				
Tip	Ød	ØD	H	L
A	14	24	5,5	6,3
A	18	28	7,0	8,0
A	20	30	7,0	8,0
A	22	30	5,5	6,3
A	25	35	7,0	8,0
A	25	40	10,0	11,0
A	28	40	8,5	9,5
A	30	38	7,0	8,0
A	30	40	10,0	11,0
A	30	40	7,2	8,0
A	32	42	7,0	8,0
B	35	43	7,0	8,0
A	35	45	7,0	8,0
A	35	47	7,0	8,0
B	37	47	8,0	9,0
A	38	48	8,0	9,0
A	40	48	9,0	9,0
A	40	50	7,0	8,0
A	45	53	8,0	9,0
A	45	55	10,0	11,0
A	45	55	7,0	8,0
A	45	58	9,0	10,0
B	50	58	11,5	12,5
A	50	60	7,0	8,0
A	50	62	8,0	9,0
A	50	63	9,0	10,0
A	50	65	10,0	11,0
A	55	63	8,0	9,0
A	55	65	10,0	11,0
A	55	70	10,0	11,0
A	56	71	11,5	12,5
A	60	70	7,0	8,0
A	60	72	9,0	10,0
B	65	75	8,0	9,0
A	70	80	10,0	11,0
A	70	85	11,0	12,0
A	70	85	11,5	12,5
B	75	90	11,5	12,5
A	80	95	10,0	11,0
A	80	95	11,0	12,5
A	90	105	12,0	13,0
A	100	120	12,0	13,0
A	130	110	12,0	13,0

Tip M2/AU				
Tip	Ød	ØD	H	L
A	16	24	5,5	6,3
B	16	24	5,5	6,3
A	18	25	5,0	5,7
B	18	26	5,5	6,3
A	18	26	6,0	7,0
A	22	32	8,0	9,0
B	25	33	7,0	8,0
A	25	35	7,0	8,0
A	28	36	8,0	9,0
A	28	38	7,0	8,0
A	30	40	10,0	11,0
B	32	40	7,0	8,0
B	32	42	7,0	8,0
A	32	45	10,0	11,0
B	38	50	7,5	8,5
A	40	50	10,0	11,0
A	40	52	10,0	11,0
A	45	55	10,0	11,0
B	40	55	10,0	11,0
A	50	60	10,0	11,0
A	60	70	10,0	11,0
B	60	75	11,8	13,0
B	60	68	7,0	8,0
B	60	80	11,8	13,0
A	70	80	10,0	11,0
A	70	80	7,0	8,0
A	70	82	9,0	10,0
A	80	90	7,0	8,0
B	80	95	11,5	12,5
B	90	102	9,0	10,0
A	90	105	11,5	12,5